



Audi Centre Newcastle

Automotive Gallery Newcastle Pty Ltd

83-85 Parry Street, NEWCASTLE WEST NSW 2302
 TEL: (02) 4969 8500 FAX: (02) 4969 8600
 ACN: 117 770 715 ABN: 67 797 456 358

TAX INVOICE No.	Debtor Code CSW	Rego CHZ81V	Build MMY \ Make \ Model Description 0812 \ AUDI \ Q7 3.0 TDI QUATTRO 8-SPEED TIPTRONIC	Model Code 4LB0GA/13	Body Type WAGON	Colour MUGELLO BLUE
R 18847*	MANTILLA MEDICAL FT PTY LTD 17 VALLEY CRESCENT GLENDALE NSW 2285		First Rego Date 31-AUG-12	Order No.	ABN #	Phone 0439383622
Create Date 17-JUN-14	JOHNMMD@MANTILLAMEDICAL.COM		VIN WAUZZZ4L3DD002407	Engine #	Chassis 002407	Internal A/C
Close Date 17-JUN-14			Contract Expiry 0 kms	Contract Provider	Contract #	
Service Advisor RYAN BATES (13)	Franchise # 1	Kilometres 58441	Warranty Expiry 30-AUG-15 0 kms	Selling Dealer PARRA	Time In 0730	Time Req. 0730

Type	Detail	Amount
------	--------	--------

1	RJ 60K	464.64
---	---------------	--------

CARRY OUT 60000KM SERVICE AS PER SCHEDULE
 =====
 CARRIED OUT 60000KM SERVICE AS PER SCHEDULE

FRONT AND REAR WIPERS SLIGHTLY STREAKY, RECOMEND REPLACEMENT IN NEAR FUTURE
 FRONT BRAKE PADS AND ROTORS AND REAR BRAKE PADS AT 4MM AND MAY REQUIRE
 REPLACEMENT BEFORE NEXT SERVICE. CUSTOMER TO RETURN WHEN BRAKE PAD LIGHT
 ILLUMINATES ON DASH
 BRAKE FLUID FLUSH DUE AT TIME OF BRAKE REPLACEMENT

Part Number	Description	Quantity	
059198405	OIL FILTER	1	28.15
N0138157	WASHER	1	3.83
G052164M2	AUDI GEN WASH ADD	1	9.60
7H0 819 631A	POLLEN FILTER	1	50.98
8K0127400A	FUELFILTER	1	56.84
7L0129620A	FILTERELEM	1	42.55
Sundries		Quantity	
AUDI SLX SYNTHETIC ENGINE OIL		8.2	238.21
HAZARDOUS WASTE DISPOSAL & SUND		1	13.64
		Job Total	908.44

2	RJS S18847 ROTATE	2,363.64
---	--------------------------	----------

* CARRY OUT REPLACEMENT OF 4 X TYRES WITH PIRELLI S VERDAE 275/45/20 AND NITROGEN
 FILL

Job Total 2,363.64

3	RT TY	0.00
---	--------------	------

TYRE BRANDPIRELLI..... TYRE SIZE275/45/20.....

METHOD OF PAYMENTCARD.....

DRIVER.....ANECITO.....

HAND WASH..YES...

SERVICE BOOK PRESENT..YES...

DAMAGE REPORT COMPLETED..YES...

QUALITY CHECK COMPLETED BYNATHAN..... DATE17/06/2014.....KMS ON COMPLETION
 OF ROAD TEST.....58,444.....

Job Total 0.00

4	RT NSM	0.00
---	---------------	------

* CHECKED OUTSTANDING SERVICE MEASURES
 CHECKED AND FOUND VEHICLE TO HAVE NO OUTSTANDING SERVICE MEASURES

Job Total 0.00



Audi Centre Newcastle

Automotive Gallery Newcastle Pty Ltd

83-85 Parry Street, NEWCASTLE WEST NSW 2302
TEL: (02) 4969 8500 FAX: (02) 4969 8600
ACN: 117 770 715 ABN: 67 797 456 358

TAX INVOICE No.	Debtor Code CSW	Rego CHZ81V	Build MMY \ Make \ Model Description 0812 \ AUDI \ Q7 3.0 TDI QUATTRO 8-SPEED TIPTRO	Model Code 4LB0GA/13	Body Type WAGON	Colour MUGELLO BLUE
R 18847*	MANTILLA MEDICAL FT PTY LTD 17 VALLEY CRESCENT GLENDALE NSW 2285		First Rego Date 31-AUG-12	Order No.	ABN #	Phone 0439383622
Create Date 17-JUN-14	JOHNMMMD@MANTILLAMEDICAL.COM		VIN WAUZZZ4L3DD002407	Engine #	Chassis 002407	Internal A/C Stock #
Close Date 17-JUN-14			Contract Expiry 0 kms	Contract Provider		Contract #
Service Advisor RYAN BATES (13)	Franchise # 1	Kilometres 58441	Warranty Expiry 30-AUG-15 0 kms	Selling Dealer PARRA	Time In 0730	Time Req. 0730

Type	Detail	Amount
5 RJ	WA CARRY OUT 4 WHEEL ALIGNMENT =====	84.00
	CARRIED OUT 4 WHEEL ALIGNMENT AS REQUIRED	
Job Total		84.00

YOUR NEXT SERVICE IS DUE AT 75,000 KILOMETRES OR ON 17/06/2015

Total Labour	\$	548.64
Total Sublet	\$	2,363.64
Total Parts	\$	191.95
Total Sundry	\$	251.85
Sub Total	\$	3,356.08
GST	\$	335.61
Rounding	\$	0.00
Invoice Total	\$	3,691.69
TOTAL DUE	\$	3,691.69

Audi Centre Newcastle
83-85 Perry Street
Newcastle West NSW 2302

Work Order: A18847
 Customer Name: MANTILLA
 VIN: WAUZZZ4L3DD002407
 Technician: GF
 Odometer: 58441
 Make/Model/Stock No: CHZ81V
 Date: 17.6.14 12:46



WAUZZZ4L3DD002407

Audi : Q7 : Standard Suspension (1BA) : 2007-

Front : Left

Actual	Before	Specified Range
-0°17'	-0°30**	-0°25' 0°05'
8°11'	8°11'	7°40' 8°20'
0°06'	0°10'	0°02' 0°12'
10°30'	10°43'	
10°13'	10°13'	
		-1°50' -0°50'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°01'	0°09**	-0°25' 0°05'
7°03**	7°03**	7°40' 8°20'
0°06'	0°05'	0°02' 0°12'
10°44'	10°33'	
10°43'	10°43'	
		-1°50' -0°50'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°16**	-0°39**	-0°10' 0°10'
1°08**	1°08**	-0°30' 0°30'
-0°13'	0°10'	
0°12'	0°15'	0°04' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°27'	-0°10**	-1°40' -1°00'
0°13'	0°16'	0°07' 0°17'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°25'	-1°40' -1°00'
0°16'	0°15'	0°07' 0°17'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°04'	1°15**	-0°20' 0°20'
0°29'	0°31'	0°14' 0°34'
-0°02'	0°01'	-0°04' 0°04'

* This value is not within specification. Tire wear, handling and safety problems may result.

Customer Name	Chassis number	Kilometres	Repair order no.
MARTILLA		5944	A18847
Work must be carried out in accordance with the latest Maintenance Manual specifications			
Change brake fluid (every 2 years); Note: Never remove strainer from brake fluid reservoir			OK
Visual Check			
Check for campaigns; list any outstanding and rectify: _____			
Front lights - Check function: Side lights, dipped beam, main beam, fog lights, turn signals, hazard warning lights, Adaptive headlights, Daytime running lights.			✓
Rear lights - Check function: Brake lights, tail lights, reversing lights, rear fog light, number plate light, turn signals, hazard warning lights, luggage/load compartment lights			✓
Interior and instrument lighting, warning lamps and horn: Check function			✓
Windscreen wiper blades: Check for damage - change in consultation with customer			✓
All wheels including the spare: Check condition and wear pattern of tyre			✓
Enter tyre tread depth: FL 7 mm, FR 7 mm, RL 7 mm, RR 7 mm, Spare _____ mm			✓
Engine (from above) and engine compartment: Carrying out visual check for leaks and damage check Plenum chamber drain			✓
Brake system (from below): Visual check for leaks and damage			✓
Under body protection: Visual check for damage			✓
Exhaust system: Visual check for leaks, security and damage			✓
Engine, gearbox, final drive, steering, joint protective boots/bellows: Visual check for leaks and damage			✓
Check Ribbed belt			✓
Maintenance List			
Read fault memories with fault reader VAS 5051/5052/6150			✓
Service display: Reset inspection service			✓
Door hinges, arresters, lock cylinders and bonnet catch: Grease			✓
Windscreen wash/wipe system and headlight washer system: Check function and spray jet settings and replenish with additive as required			✓
Tyres (incl. spare wheel): Inflate to the correct pressure			✓
Track rod ends: Check play, security and boots			✓
Ball joints: Check play and ball joint boots for leaks and damage			✓
Engine oil: Drain or extract, renew oil filter and replace sump plug			✓
Front (automatic gearbox) and rear (quattro) final drive: Check oil level, replenish oil if necessary			✓
Manual transmission: Check oil level, replenish oil if necessary			✓
Brake pads/linings and brake discs: Check thickness F: 4 R: 4			✓
Engine oil: Replenish (after replenishing top-up to max mark if necessary)			✓
Battery: Check terminals clean & tight, electrolyte level and top-up with distilled water if necessary, renew seat bolts Q7 only			✓
Anti-freeze: Check frost protection and coolant level/anti-freeze specification -25 degree. Actual value (measured value): -23 degree			✓
Dust and pollen filter: Renew			✓
Hydraulics: Check oil level and for leaks, replenish hydraulic oil if necessary			✓
Remote battery - replace. (Vehicles with advanced key only)			✓
Rollover protection test and reset - A5 Cabriolet and R8 Spyder			NA
Sunroof guides clean and lubricate as per ELSA and test drains are free from blockage			NA
Fill adBlue tank (Vehicles with adBlue system only)			NA
Sticker: Complete next service sticker (including next change of brake fluid)			NA
Additional Items 30k			
Spark plugs replace - TTRS only			
Fuel filter replace - Q7 6.0TDI only			
Air cleaner: Clean air cleaner housings and renew filter elements - RS4, R55, R56 and R8 only			
Additional Items 60k			
Air cleaner: Clean air cleaner housing and renew filter element			
Haldrax coupling: Change oil - Quattro TT, Q3 and A3 only			✓
Spark plugs: Replace - All non FSI engines and 1.2TFSI, 1.4TFSI, All gen 3 4 cyl and CDN, S3, TTS and 4.0TFSI			NA
S-Tronic oil: Change - All models except 0AM (Change filter on all 8P A3& B) TT Models)			NA
Sports diff oil Replace - RS4 and R55 only			NA
Gear oil Replace - RS4 and R55 only			NA
Multi transmission oil: Renew oil (oil level tube on A4 & A5 only)			NA
Fuel filter: Renew - All models with an external filter			NA
Additional Items 90k			
Spark plugs: Renew all FSI models except 1.2TFSI, 1.4TFSI, All gen 3 4 cyl and CDN, S3, TTS and 4.0TFSI			
Other Additional Items			
Diesel particulate Filter: Reading out ash deposit mass (2.7TDI/3.0TDI After 210,000km then every 30,000km)(2.0TDI after 180,000km then every 30,000km)			
All petrol engines: Add Audi Fuel additive to fuel tank (refer to etka for part number)			
Timing, auxiliary and supercharger belt: Replace every 4 years or 90,000km whichever comes first, refer ELSA for exact tensioner/roller replacement requirements			NA
Adaptive cruise control: Carry out misalignment check refer GFF MVB's			NA
Tyre repair set: Check expiry date (renew used bottles) RS Models, S05, Allroad & TT (at time of print)			NA
Quality check: Carry out road test			NA

Comments

BRAKE PADS AT 4MM : MAY NOT LAST TILL NEXT SERVICE

17.6.14 
Date/Signature (Technician)

 17/6/14
Date/Signature (Quality Control)

J285 - Inspection with oil change

VIN	WAUZZZ4L3DD002407	Model year	2013 (D)
Manufacturer	Audi	Variant	2013 (D)
Model	Audi Q7 2007>	Engine	CRCA 3.0l TDI / 180 kW

**Active step:****Preparation steps****Note:**

- Print out this screen view by choosing **⇒Print⇒Screen** and attach the printout to the tracking/invoicing file.

You will need this documentation in the event of any warranty claims.

Chassis number: WAUZZZ4L3DD002407

Current kilometre reading: 58440 km

Current date: 925

Service exceeded distance: 0 km

Service exceeded time: 0 Days

17-Jun-2014 11:24:01

ODIS